


PCI (PC Bus) Components

This page is furnished to act as a guide to those who require a servo control system. This diagram represents a suggested configuration and a cross reference of all required components.

TOP VIEW:



This is the standard way to set up the system.

A complete Servo Motion Control System consists of the following:

- Servo Card 400 Controller (page 158), or equivalent
- SAC Software package (included with Servo Card 400), or other programming language (page 171)
- Servo Power Box (page 156)
- Servo Motor Amplifiers, one per axis (page 157)
- Servo Motor/Encoder cables, one per axis (page 166)
- IBM Compatible PC with PCI slot